



The following risks are identified as unusual or unfamiliar to a competent contractor

**CONSTRUCTION RISKS**  
There are no significant or unfamiliar risks


**DEMOLITION RISKS (FUTURE)**  
There are no significant or unfamiliar risks

It is assumed that all work will be carried out by a competent contractor working, where appropriate, to an approved method statement


**Notes:**

-  Irredeemable Timber
-  Other Areas of Damage


Refer to engineer's report by Clive Haywood of Frank. W. Haywood & Associates




East Elevation




North Elevation



West Elevation



South Elevation






REV	DETAILS	DATE	CHECKED



01543 254357 - mail@bhbarchitects.co.uk

Holy Trinity Church Centre (Old Blue Coat School)		DRAWING NO.
Lantern Damage Report		3433 - 03
Holy Trinity Church	REV	DATE
		Dec '18

<b>PRELIMINARY</b>	DRAWN	CHECKED	SCALE
	MR	AH	1:50 @ A2

		The copyright of this drawing and design is vested in the Architect and must not be copied or reproduced without written consent. All dimensions given are to be verified on site by the responsible contractor. Do not scale dimensions from this drawing.	
---	---	---	---