



**1 FRONT ELEVATION VIEW**  
1 : 100



**2 REAR ELEVATION VIEW**  
1 : 100



**3 ELEVATION FROM RIGHT VIEW**  
1 : 100

Rev	Description	Date
B	Condensers now fixed to wall. Window adjacent escape door removed, signage added to front gable, parking layout chaged, wall lightis added.	24.06.19
A	Hedge changed to fencing, condensers moved parking markings altered	15.06.19